





**NOTES**

NO DESIGN DEFICIENCIES IDENTIFIED WITHIN THE I-215 SEGMENT OF THE STUDY AREA. FOR DESIGN DEFICIENCIES AT THE SR-201/I-215 INTERCHANGE, SEE FIGURE 1-6.



**ROADWAY AND SAFETY DEFICIENCIES  
I-215 SEGMENT  
3500 SOUTH TO I-80**

Figure 1-7